

SAFETY TALK

TOOL BOX





UPTO YOU!!!

The most common causes of hand injuries:

- Carelessness
- Disregard for Safety Procedures
- Distractions

CONVIRON'S SAFETY RULES

- 1. Wear cut resistant gloves where risk of injury to your hands exist. The only exception is when you are working on equipment/machines with rotating parts.
- 2. Never remove machine safeguards. Do not put your fingers or your hands through, under, over, or around the guard.
- 3. When you're using a nail gun, stapler, utility knife etc, keep your other hand a safe distance away.
- 4. Be aware of pinch points.
- 5. Be aware of hot surfaces (while soldering, brazing, using the heat gun etc.)
- 6. Be aware of task specific PPE. For more info see PPE Policy on Conviron Universe, Gecko Screens or ask your Supervisor.